This checklist is used to facillitate and record the testing of used computers for key functionality.

Database ID: 12365 Manufacturer: Dell-Inc. Date: August 19, 2026
Model: Latitude 5420 Serial#: B9DT1J3 Version: 3.24.0 beta

B9DT1J3

## Cosmetic Categories

| | |
|---|---|
| ID: Incomplete / Damaged ☐ | x Send for Material Recovery |
| LVR: Low Value Remarketable ☐ | x Cosmetic blemishes are consistent with wear, including multiple dents, discoloration, and light to heavy scratches<br>x Damage to latches, hinges, keyboards, etc.<br>x Some parts, panels, bezels, or covers may be missing<br>OR<br>x Cosmetic blemishes include scratches and/or other surface imperfections from consistent use, but equipment is in good condition overall<br>x Minor wear of labeling may be visible<br>x Small dents and small areas of discoloration may be present from the removal of tags<br>x No damage to latches or hinges, nor any missing parts, panels, bezels, or covers |
| HVR: High Value Remarketable ☑ | x Cosmetic blemishes include minor scratches and/or other surface imperfections from consistent use, but equipment is in good condition<br>x Minor wear of labeling may be visible<br>x Minor dents and areas of discoloration from the removal of tags<br>x No missing parts<br>OR<br>x Overall excellent cosmetic condition<br>x May have light scratches or other minor blemishes from normal wear<br>x Minor cosmetic blemishes have no impact on the system's overall functionality or performance<br>x Fully cleaned with all non-original labels removed<br>x No missing parts |

## Function Categories

| | |
|---|---|
| INF: Incomplete / Nonfunctional ☐ | x Send for Material Recovery |
| RI: Remarketable Incomplete ☐ | x A subset of the primary functions of the device that an ordinary user of the device expects to function are verified working through manual or software tests<br>x Software may not be loaded or configured<br>x Hardware required for key functions to be tested may have been removed after testing (e.g. Hard Drive)<br>x May be missing components or parts not essential to key functions<br>x Secondary functions may not be tested or working<br>x May not include Focus Materials (e.g. Battery) that are not working or not tested<br>x All missing components or parts will be listed for each item |
| RC: Remarketable Complete ☑ | x All hardware is tested and verified working through manual or software tests<br>x No missing or damaged components or parts<br>x Software not loaded or configured<br>x No hardware defects |

| Key Component | Technical Specifications | Other description |
|---|---|---|
| Hard Drive | 476.9G NVMe Format | 10177 |
| HDD Info | NVMe | |
| RAM | 31.6G | |
| LCD Screen | 1920x1080 | |
| Battery | 66% | |
| CPU | 11th Gen Core i5-1145G7 | 1500MHz |
| Wi-Fi | Yes | bluetooth |

***Missing or removed components after testing must be disclosed to the buyer prior to sale**

**Additional Information:**
Supplier Code: **STG**
Purchase Number: **8CDS7424A**

Database ID: **12365**
Scan QR code before shipping this unit for sale
8.0.29 Rev 2